



1997 Cessna Citation X S/N 750-0026

Make Offer

Airframe:

Airframe (Hours as of October 2018)
Hours 11,312
Landings 7234
Airframe enrolled on ProParts (\$738.00/hr.)
CESCOM maintenance tracking

Engine/APU Specs:

Engines (Hours as of October 2018)
Engines are enrolled on Rolls Royce Corporate Care (\$293.04/hr. per engine)
Rolls-Royce – AE3007C
Serial Number: CAE330055
Hours 10,511
Cycles 6553

Serial Number: CAE330054

Hours 10,517
Cycles 6510

Auxiliary Power Unit (Hours as of October 2018)
APU is enrolled on Honeywell MSP (\$116.21/hr.)
Honeywell 36-150
Serial number: P189
Hours: 10,264

Avionics/Radios:

Primus 2000 - Five EFIS Displays	Honeywell EGPWS w/ Windshear
Dual EICAS Digital Autopilot / Flight Director	Aircell Axxis Phone System
Dual Integrated Primus II Radios w/ 8.33	Global AFIS
Dual Integrated Nav RNZ850	SSFDR Flight Data Recorder
Dual RMU RM855	Coltech CSD 714 Selcal
Dual RCZ-850 ADF	Honeywell AA300 Radio Altimeter
Dual DME-850	Litton Three Frequency ELT
Dual Honeywell XS-850 Mode S Transponder	Primus A200S Cockpit Voice Recorder
Dual Honeywell FMZ-2000 FMS	A.O.A Computer
Honeywell TCAS II v. 7.0	Honeywell DL-950 Data Loader
Dual KHF 950 HF Radio	

Additional Equipment:

RVSM-Capable	Airshow 4000 Cabin Information System
Winglets	Wiggins Modification
Aileron Regearing Modification	Metric Dipstick
Extended Range Oxygen	EASA/JAA Baggage Door Modification
Pulse Lights	Dual DVD Entertainment System
Thrust Reversers	Provisions for Dual EFB & XM Wx Charts in Cockpit
Split Buss Wiring Modification	Tail Logo Flood Lights
Dual Use 110/240v Outlets in Cabin	Dual Nickel-Cadmium Batteries
EASA/JAA Window Modification	(2) Skylounger Cabin Sleep System

Optional Service Bulletin Upgrades (Subject to Sales Price – Completed during Pre-Purchase Inspection):

Honeywell FMS 6.1 WAAS LPV (SB750-34-59)
ADS-B Out (SB750-34-58)
Dual Honeywell Laseref IV (SB750-34-57)

Maintenance:

Document 2,3,4,7,8,9,10,13,15,18,19,21,34,36 Next Due: Mar-2019.
Document 11 Next Due: Mar-2021
Document 5 Next Due: Sep-2021
Document 12 Next Due: Feb-2020



Exterior:

Overall Snow White with Las Vegas Gold Metallic, Coral Red Pearl & Dark Blue Metallic Stripes. Repainted in 2008.

Interior:

Tastefully appointed 9-passenger interior, with a high gloss walnut-burl wood, desert colored leather seating, beige fabric headliner, a light brown textured fabric sidewalls and earth tone carpeting. There is a forward refreshment center with ample storage and microwave. A single side facing seat across from the entry door and an 8-place club seating arrangement, with four executive tables. The aft externally serviceable flushing lavatory poses polished gold hardware with vanity cabinet. Refurbished in 2009.

Preliminary Specification Subject to Verification Upon Inspection and Prior Removal From Market

BASIC VARIABLE COST DATA	
Airframe Maintenance Per Hour	523.00
Engine / APU Maintenance Per Hour	754.00
Fuel Cost @ \$4.25 Per Gallon based on 372.00 (Gallons Per Hour)	1,581.00
Crew Misc.	270.00
Total Variable Cost Per Hour	3,128.00
Cost Per NM	6.12
ADDITIONAL AIRCRAFT INFORMATION	
Baggage Capacity External / Internal (Cubic Feet)	82 / 0
Cabin Height (Feet)	5'8"
Cabin Width (Feet)	5'6"
Cabin Length (Feet)	23'11"
Cabin Volume (Cubic Feet)	745.40
BASIC AIRCRAFT PERFORMANCE DATA	
Seats Full Range (NM / SM)	2,817 / 3,242
Ferry Range (No Payload) (NM / SM)	3,046 / 3,505
Balance Field Length* (Take-off Distance in Feet)	5,343.00
Landing Distance (Feet)	3,584.00
Normal Cruise Speed (KTS / MPH)	511 / 588
Long Range Cruise Speed (KTS / MPH)	458 / 527
Service Ceiling (Feet)	51,000.00

*Data Provided by Aircraft Cost Calculator



The Barrieau Group
WHEN INTEGRITY MATTERS





The Barrieau Group
WHEN INTEGRITY MATTERS





The Barrieau Group
WHEN INTEGRITY MATTERS





The Barrieau Group
WHEN INTEGRITY MATTERS

